

## Benötigte Bauteile für 100 Stck. 3DO Umbau

Menge	Bauteilbez.	Bürklin-nr.	Preis	Seite	Spoerle-nr.	Preis	Seite
300	74 HCT 245	62 S 8876	219,--	O 55	CD74HCT245E	186,--	A01.104
100	74 HCT 14	62 S 8762	35,--	O 54	CD74HCT14E	39,--	A01.103
100	74 HCT 123	62 S 8798	66,--	O54	CD74HCT123E	54,--	A01.103
100	1 N 914	26 S 7525	8,--	O 24	1N4148	30,--	A01.344
300	2 K 00, 1%	30 E 321	18,--	E 16	MRS25, ...	13,50	P01.012
300	4 K 02, 1%	30 E 351	18,--	E 16	MRS25, ...	13,50	P01.012
300	8 K 06, 1%	30 E 380	18,--	E 16	MRS25, ...	13,50	P01.012
300	16 K 2, 1%	30 E 409	18,--	E 16	MRS25, ...	13,50	P01.012
300	32 K 4, 1%	30 E 438	18,--	E 17	MRS25, ...	13,50	P01.012
300	63 K 4, 1%	30 E 466	18,--	E 17	MRS25, ...	13,50	P01.012
300	127 K, 1%	30 E 495	18,--	E 17	MRS25, ...	13,50	P01.012
300	255 K, 1%	30 E 524	18,--	E 17	MRS25, ...	13,50	P01.012
100	5 K 6, 5%	17 E 290	3,51	E 9	CR 25, ...	2,60	P01.012
100	6 K 8, 5%	17 E 295	3,51	E 9	CR 25, ...	2,60	P01.012
300	100 nF, Keramik	53 D 3648	51,--	D 48	EC05ZD0104K	66,--	P04.018
100	3,3 nF, Keramik	53 D 3630	18,--	D 48	EC04ZE0332K	22,--	P04.018
100	330 pF, Keramik	53 D 3618	17,--	D 48	EC04CE0331K	18,--	P04.018
200	100 pF, Keramik	53 D 3612	34,--	D 48	EC04CE0101K	36,--	P04.018
35	LP, 100 x 160, 0.5mm	11 H 734	107,45	H 36	-----	---	---